


*Installed Halon
Systems*



*HALON IS A SEVERE
OZONE DEPLETING
SUBSTANCE*

HALON

- MONTREAL PROTOCOL OF 1987
 - ◆ ALL HALON PRODUCTION CEASED AS OF JAN 1994
 - ◆ IN 1996, THE US NAVY HAD 1.6 MILLION LBS OF HALON 1301 IN STORAGE (ENOUGH TO LAST 30 YEARS)
- ALTERNATIVES
 - ◆ FM-200
 - ◆ HIGH PRESSURE WATER MIST

HALON

- HOW TO GET (AND GET RID OF) HALON 1301
 - ◆ COMNAVSUPSYSCOM
MECHANICSBURG 111211Z AUG 99
IDENTIFIED DSC RICHMOND AS
THE ODS RESERVE CENTRAL
POINT OF ISSUE
 - ◆ REPLACEMENT AGENT IS
AVAILABLE FREE OF CHARGE

HALON

- 1 1 - NUMBER OF CARBON ATOMS
- 3 2 - NUMBER OF FLUORINE ATOMS
- 0 1 - NUMBER OF CHLORINE ATOMS
- 1 1 - NUMBER OF BROMINE ATOMS

**ONE REPORTED FATALITY FROM
“HUFFING”
HALON 1211 ONBOARD A CV!**

TYPES OF HALON

■ HALON 1211

- ◆ USED PRIMARILY ON FLIGHT AND HANGAR DECKS ON CV AND BIG DECK AMPHIBS
- ◆ ALSO FOUND IN LCACs AND MHCs
- ◆ NOT USED IN TOTAL FLOODING SYSTEMS
- ◆ HIGH LIQUID DENSITY ALLOWS ITS USE IN PORTABLE EXTINGUISHERS

HALON 1301

■ CHARACTERISTICS

- ◆ EXTINGUISHES FIRE BY INTERRUPTING THE UNINHIBITED CHAIN REACTION OF COMBUSTION
- ◆ COLORLESS, ODORLESS
- ◆ 5 TIMES DENSER THAN AIR
- ◆ NON-CONDUCTIVE

HALON 1301

■ ADVANTAGES

- ◆ VERY EFFECTIVE ON LARGE CLASS “B” FIRES
- ◆ SPACE CLEAN UP IS EASY
- ◆ EASILY MAINTAINED
- ◆ SAFER THAN CO₂ FLOODING SYSTEM

HALON 1301

■ DISADVANTAGES

- ◆ SEVERE OZONE DEPLETING POTENTIAL
- ◆ INEFFECTIVE AGAINST CLASS “D” FIRES
- ◆ TOXIC IN DECOMPOSED STATE
 - ☞ WHEN EXPOSED TO TEMPS $>900^{\circ}\text{F}$
 - ☞ HYDROGEN FLUORIDE, HYDROGEN BROMIDE (NO MORE DANGEROUS THAN NORMAL BYPRODUCTS OF COMBUSTION IN FIRE AFFECTED SPACE)

HALON 1301

◆ SLIGHTLY TOXIC IN NON-DECOMPOSED STATE

☞ UP TO 7% CONCENTRATION

- MINIMAL NERVOUS SYSTEM EFFECTS

☞ 7-10% CONCENTRATION

- DIZZINESS/TINGLING OF EXTREMITIES, INDICATIVE OF MILD ANESTHESIA

HALON 1301

◆ SLIGHTLY TOXIC IN NON-DECOMPOSED STATE

☞ >10% CONCENTRATION

- PRONOUNCED DIZZINESS / POSSIBLE UNCONSCIOUSNESS

☞ No significant adverse health effects have been reported from the use of HALON 1301 as a fire extinguishing agent since it was introduced approx. 30 years ago

USS GARY (FFG-51)

CLASS B FIRE #2 SSDG ENCLOSURE

- Underway Operations Arabian Gulf
24 September 1995
- Initially reported as Class B fire, then identified as Class A . When extinguished, fire determined to be Class C fire.
- Activation of primary Halon from CCS failed due to faulty time delay.

USS GARY (FFG-51)

CLASS B FIRE #2 SSDG ENCLOSURE

- Order to bypass time delay not accomplished, fireteam failed to hear order.
- DCA ordered release of reserve Halon, attempt to do so was unsuccessful due to mislabeled actuator bottles in CCS. (18M-4R) not properly accomplished in 2nd QTR 1995.

USS GARY (FFG-51)

CLASS B FIRE #2 SSDG ENCLOSURE

- CCS reported 600 PSI on all bottles, prompting 2 more attempts to release Halon. Both attempts fail, third attempt succeeds when time delay is bypassed and reserve agent (labeled primary) is released.
- Number 1 AFFF Station failed due to electrical ground.

USS GARY (FFG-51)

CLASS B FIRE #2 SSDG ENCLOSURE

- Number 2 AFFF Station without power due to electrical isolation. Casualty power rigged but not energized due to concerns about overloading only operating diesel.
- ALL power lost throughout ship due to loss of only online generator.

USS GARY (FFG-51)

CLASS B FIRE #2 SSDG ENCLOSURE

■ Equipment Problems:

- ◆ 22 of 27 lights on firefighting helmets failed to operate.
- ◆ Crew members attempted to load OBA canisters improperly.
- ◆ P-250s failed to operate.

HALON 1301

- AGENT APPLICATION
 - ◆ MAIN ENGINEERING SPACES
 - ◆ FLAMMABLE LIQUID STOREROOMS
 - ◆ SSDG/GTG/GTM ENCLOSURES
 - ◆ 5-7% CONCENTRATION IN MANNED SPACES
 - ◆ 18-20% CONCENTRATION IN UNMANNED SPACES

HALON 1301

- MANUFACTURERS

 - ◆ ANSUL

 - ◆ KIDDE

- ANSUL VALVE ACTUATORS

 - WILL FIT KIDDE BOTTLES BUT

 - WILL NOT DISCHARGE HALON

- KIDDE VALVE ACTUATORS

 - WILL NOT FIT ANSUL BOTTLES

HALON 1301


■ SYSTEM DESIGNS

- ◆ MODULAR - ONE NOZZLE FOR EACH HALON BOTTLE
- ◆ BANK I - ONE BANK OF CYLINDERS LOCATED IN PROTECTED SPACE
- ◆ BANK II - PRIMARY/SECONDARY BANKS LOCATED IN PROTECTED SPACE
- ◆ BANK III - PRIMARY/SECONDARY BANKS LOCATED IN A SEPARATE ROOM (SERVES MORE THAN ONE SPACE)

HALON 1301 SYSTEM COMPONENTS


- CO₂ ACTUATION CYLINDER
 - ◆ 5 LB CHARGE OF CO₂
 - ◆ PROVIDES MOTIVE FORCE FOR SYSTEM ACTIVATION
 - ◆ DISCHARGES THROUGH CUNI TUBING AND A CHECK VALVE INTO THE CO₂ ACTUATION MANIFOLD

CO₂ ACTUATION CYLINDER



MANUAL

*CO₂ Actuation bottles
(Primary / Reserve)*



HALON 1301 SYSTEM COMPONENTS

- CO₂ ACTUATION PIPING VENT
 - ◆ 1/32" VENT HOLE THAT ALLOWS FOR CO₂ PRESSURE TO VENT OFF AND ENABLE RESETTING OF PRESSURE SWITCHES

HALON 1301 SYSTEM COMPONENTS


- DISCHARGE TIME DELAY DEVICE (TDD)
 - ◆ ALLOWS TIME FOR PERSONNEL TO SECURE COMPARTMENT ACCESSES
 - ◆ ALLOWS VENTILATION TIME TO “COAST DOWN”
 - ◆ MACHINERY SPACE = 60 SECONDS
 - ◆ NON-MACHINERY SPACE = 30 SECONDS

HALON 1301 SYSTEM COMPONENTS

- DISCHARGE TIME DELAY DEVICE (TDD)
 - ◆ CARLETON TIME DELAY ONLY AUTHORIZED MODEL
 - ◆ CARLETON TIME DELAY IS NOT REPAIRABLE BY SHIP'S FORCE (CNSL 210500ZSEP96)
 - ◆ PMS ALLOWS FOR 60 PLUS OR MINUS 10 SECONDS / 30 PLUS OR MINUS 5 SECONDS

TIME DELAY

*CARLETON TIME
DELAY*



HALON 1301 SYSTEM COMPONENTS

- TIME DELAY DEVICE BYPASS VALVE
 - ◆ NORMALLY CLOSED BALL VALVE; CIRCLE X-RAY CLASSIFICATION (SHOULD BE ON CCOL)
 - ◆ OPERATED WHEN TDD FAILS TO OPERATE OR TIME TO DISCHARGE EXCEEDS 70 SECONDS FOR A MAIN MACHINERY SPACE

HALON 1301 SYSTEM COMPONENTS

- TIME DELAY DEVICE BYPASS VALVE
 - ◆ USED WHEN APPLYING HALON AFTER SPACE EVACUATION HAS BEEN EFFECTED WHEN ALL ACCESSES ARE SECURED AND VENTILATION IS STOPPED

HALON 1301 SYSTEM COMPONENTS

■ PRESSURE SWITCHES (3)

◆ ALARM / INDICATOR SWITCH

- ☞ SOUNDS ALARM IN PROTECTED SPACE AS WELL IN CONTROLLING STATIONS


- ☞ ENERGIZES ROTATING BEACONS IN PROTECTED SPACE

◆ VENT SHUTDOWN SWITCH


◆ HALON RELEASE INDICATOR SWITCH

◆ QUARTERLY TEST OF “BELLS AND WHISTLES”

PRESSURE SWITCH



HALON INDICATOR LIGHT PANEL




POWER AVAILABLE

SYSTEM ACTIVATED

HALON DISCHARGED

HALON SYSTEM




Pressure Switches

- *Vent Shutdown*
- *Pre-discharge Alarm*
- ***Vent Damper control***
- *Discharge Alarm*

TDD Bypass Valve

CO₂ Actuation Bottle



TDD

HALON 1301 SYSTEM COMPONENTS

■ HALON CYLINDER

- ◆ PRESSURIZED WITH NITROGEN TO 600-675 PSI AT 70⁰F
- ◆ COMES IN 10/15/60/95 AND 125 LB SIZES
- ◆ NON-SHATTERABLE STEEL CYLINDERS
- ◆ COLOR CODED RED WITH 3" WHITE STRIPE ABOVE 3" GRAY STRIPE

HALON 1301 SYSTEM COMPONENTS

- HALON CYLINDER
- PMS REQUIRES ULTRASONIC INSPECTION ON A SEMI ANNUAL BASIS
- CYLINDERS MUST BE WEIGHED UPON INITIAL RECEIPT / WHENEVER ULTRASONIC RESULTS INDICATE LIQUID LEVEL IS TOO LOW



*Halon Cylinder
Storeroom
(DDG 51 class)*


HALON 1301 SYSTEM COMPONENTS

- INSPECT CYLINDER VALVES / ACTUATORS
 - ◆ NAVSAFECEN SAFETY ADVISORY 14-95 DEFINES CRITICAL MEASUREMENTS TO IDENTIFY WHICH VALVE ACTUATORS ARE INSTALLED

HALON 1301 SYSTEM COMPONENTS

- CYLINDER VALVE ASSEMBLY AND RUPTURE DISC
 - ◆ SPOOL TYPE VALVE
 - ◆ RUPTURE DISC RELIEVES AT 2650-3000 PSI (APPROX 240⁰F)


ACTUATOR HEAD



*Wire braided
discharge
hose*



Pressure gage




HALON 1301 SYSTEM COMPONENTS

- **CYLINDER PRESSURE GAGE**
 - ◆ 0-1500 PSI
 - ◆ CYLINDER PRESSURE IS DIRECTLY PROPORTIONAL TO SPACE TEMP.
 - ◆ PMS REQUIRES INSPECTION OF CYLINDER PRESSURES MONTHLY

I. CORRESPONDING TEMPERATURE AND PRESSURE GRADUATIONS

TEMPERATURE	50°	70°	100°	125°	150°	175°	200°
PRESSURE	540	605	720	980	1320	1680	2020



HALON 1301 SYSTEM COMPONENTS

- HALON DISTRIBUTION PIPING AND NOZZLES
 - ◆ PROVIDES AGENT DISTRIBUTION THROUGHOUT SPACE
 - ◆ PIPING CONNECTED BY 1^{1/2}” STEEL BRAIDED FLEXIBLE HOSES
 - ☞ *HYDROSTATIC TESTING AT REGULAR INTERVALS PER FLEX HOSE MANAGEMENT PROGRAM NO LONGER REQUIRED / VISUAL INSPECTION ANNUALLY*

HALON 1301 SYSTEM COMPONENTS


- HALON DISTRIBUTION PIPING AND NOZZLES
 - ◆ NOZZLE ORIFICE AND BODY SIZE VARY DUE TO VOLUME OF SPACE PROTECTED AND NOZZLE LOCATION

HALON 1301

■ SPACE RE-ENTRY REQUIREMENTS

- ◆ 15 MINUTE SOAK TIME REQUIRED TO ALLOW FOR SPACE COOLING
- ◆ OBA REQUIRED FOR ENTRY
- ◆ FFE, BOOTS, GLOVES, FLASH GEAR, HELMET
- ◆ 2 CHARGED AFFF HOSES

Halon 1301 Flooding System



HALON-1301 vs FM-200

	HALON	FM-200
ODP	15	0
ATM LIFE	77	31
EFF %	3%	8.5%
RDC	5-7%	12-13%
# OF CYL	12	23
WT/VOL	1	1.9
DECOMP TEMP	900 ⁰ F	1292 ⁰ F
LOAEL	7.5%	10.5%

FM-200

- SKED FOR INSTALLATION IN FLAMMABLE LIQUID STOREROOMS ON LPD-17 / CVN-76
- DESIGNATED HFC-227ea


***FRESH WATER
STORAGE
TANK***

M

***HIGH
PRESSURE
WATER MIST***

***1000 PSI
DISCHARGE
PRESSURE***

***200 MICRON NOZZLES
PROTECTED SPACE***



HIGH PRESSURE WATER MIST

- HIGH PRESSURE WATER SPRAY (1000 PSI) DELIVERED BY A POSITIVE DISPLACEMENT PUMP THROUGH 200 MICRON NOZZLES TO EXTINGUISH THE FIRE BY COOLING
- TESTED SUCCESSFULLY ABOARD EX-USS SHADWELL IN SEP98 DURING DAMAGE CONTROL AUTOMATION FOR REDUCED MANNING TESTING

HIGH PRESSURE WATER MIST

- DURING SHADWELL TESTING SPACE TEMP WAS REDUCED FROM 900⁰F TO 130⁰F *WITHIN 30 SECONDS*
- <30 GAL WATER REQUIRED
- FIRE EXTINGUISHMENT WILL OCCUR IN SPITE OF OPEN ACCESS DOORS / CLOGGED OR BLOWN OFF NOZZLES (extinguishment time increased but occurred nonetheless)

HIGH PRESSURE WATER MIST

- TESTING INDICATES THAT EXTINGUISHMENT TIMES ARE *SHORTER* FOR LARGER FIRES
- WHEN FIRE WAS SMALL IN MAGNITUDE AND OBSTRUCTED ON 4 OF 6 SIDES EXTINGUISHMENT TIME DID NOT EXCEED 6 MINUTES

HIGH PRESSURE WATER MIST

- MINIMAL DAMAGE TO ELECTRICAL EQUIPMENT - PRELIMINARY TESTING BY HUGHES ASSOCIATES INDICATES THAT MIST SPRAY FAILED TO DAMAGE A PC FROM A DISTANCE OF 36 INCHES!
- SKED FOR INSTALLATION IN MAIN ENGINEERING SPACES ONBOARD LPD-17 / CVN-76

SUMMARY

- HALON IS A SEVERE OZONE DEPLETING SUBSTANCE
- ALL PRODUCTION OF HALON STOPPED IN 1994 / US NAVY HAS 1.6 MILLION LBS OF HALON 1301 IN RESERVE (30 YEAR SUPPLY)
- HALON 1211/ PORTABLE EXTINGUISHERS

SUMMARY

- HALON 1301
 - ◆ SYSTEM COMPONENTS
 - ◆ TYPES OF TOTAL FLOODING SYSTEMS
 - ◆ HAZARDS ASSOCIATED WITH USE
 - ◆ ALTERNATIVES

REVIEW QUESTION #1

- IF NO HALON DUMP ALARM IS RECEIVED 70 SECONDS FOLLOWING SYSTEM ACTIVATION WHAT ACTION SHOULD BE TAKEN?
- THE OPERATOR MUST OPEN THE TIME DELAY BYPASS VALVE

REVIEW QUESTION #2

- HOW CAN HALON EFFECTIVENESS BE DETERMINED FOLLOWING CLASS B FIRE EXTINGUISHMENT?
- TEMPERATURE OF SURROUNDING BULKHEADS
- CHANGE IN AMOUNT / COLOR OF SMOKE
- REDUCTION IN FIRE NOISE
- VISUAL INSPECTION THROUGH EOS / ESCAPE TRUNK WINDOWS

REVIEW QUESTION #3

- WHAT IS THE MINIMUM HALON SOAK TIME? WHY?
- 15 MINUTES
- ALLOW FOR SPACE COOLING

REVIEW QUESTION #4

- WHAT DO EACH OF THE HALON SYSTEM ALARM LIGHTS INDICATE?
- WHITE - POWER AVAILABLE TO ALARM SYSTEM
- AMBER - SYSTEM ACTIVATION HAS OCCURRED
- RED - HALON DISCHARGE

Installed Halon Systems

Unit 5.9