MONITORING TEAM KIT

AEL Range: 2-880044266 to 4267

A laminated inventory list should be provided with this kit.


MONITORING TEAM KIT

Quantity Required

KIT - MONITORING TEAM-DC


1H 0000-LL-CQA-2459

This kit identifies all equipment used for the function of providing CBR surveys in order to isolate CBR boundaries. Individual items are listed on AEL #2-880044266 and in alphabetical order in this guide.



MONITORING TEAM KIT Quantity Required 3/8" **PENCIL - CHINA MARKER BLACK** 1 doz NSN 7510-00-240-1526 6" WT. 0.5 oz VOL. 0.6 in³ Helpful Hints: Actual Inventory: SCISSORS -1/4" Thick 2 NSN 6515-00-935-7138 pr WT. 0.6 lbs. VOL. 9.4 in³ 12

Helpful Hints: Used to cut twine in monitoring operations.



Actual Inventory:


MONITORING TEAM KIT

Quantity Required


10

SIGN - CHEMICAL

1HM0000-LL-CQA-0093 (PACKAGE OF 10) WT. 1.0 lbs. VOL. 135.0 in³



Helpful Hints: Signs to be manufactured IAW NSTM 470 and NSTM 070. These signs are also available from the 3-M Co.



Helpful Hints: Signs to be manufactured IAW NSTM 470 and NSTM 070. These signs are also available from the 3-M Co.

Actual Inventory:

MONITORING TEAM KIT

Quantity <u>Required</u>

TIMER - OBA		The second secon	
NSN 4240-01-049-1024			each
WT. 0.2 lbs.	VOL 16.0 in ³		
<u>Helpful Hints:</u>			
	ar s		 1
		Actual Inventory:	
TWINE - HEMP FIBROUS			1 lb
NSN 4020-00-231-5870		4"	115
WT. 1.0 lb	VOL. 64.0 in ³		
Helpful Hints: For securing signs indicatin ease of use.	g contaminated area.	Attach to signs at appropriate MOPP level for	
		Actual Inventory:	